

SUNWING

Quality Control System

Designed By SUNWING


SUNWING Quality Control System Overview



Quality control is essential to building a WIN-WIN business and keeping long term cooperation. This article will give you a comprehensive introduction through flow chart, inspection team, inspection equipment, inspection standard, and inspection report.

Part.1 Quality Inspection Process

Quality Control Flow Chart



Strict Quality Control System

- Inspection for raw materials
- Production process inspection
- Sample inspection for mass production

Final self-inspection

Quality: Ensure the product meets the client's needs through the final sample inspection.

Packages: Ensure that the packaging is complete and clean, in line with customs transportation requirements.

 Inspection report 江苏松辉实业有限公司篱笆验货报告							
工厂名称: Name of the factory		合同号: Contract		订单号: Order number		日期: Date	
订单数量/单位: Order quantity		交货日期: Date		2017-9-6			
收货数量/单位: Inspect quantity		预计装箱日期: Loading date					
货号 Item number	数量 Quantity	色样对比 Colour comparison	叶片掉落/破损 程度 & 原因 Defect Leaf & quantity	货号 Item number	数量 Quantity	色样对比 Colour comparison	叶片掉落/破损 程度 & 原因 Defect Leaf & quantity
A-11	120	✓	2片 2片				
A-12	168	✓	1片 1片				
A-13	100	✓	1片 1片				
A-14	168	✓	1片 1片				
包装 packing status							
特殊要求 Special requirement							
货号 Item number	外观 Appearance	唛头 Shipping mark	箱规/ Ctn size	箱重 GW	装箱数 Quantity/ctn		
A-11	✓	5451120	7.310	2.300	2.300		
A-12	✓	5451120	7.110	2.100	2.100		
A-13	✓	5451120	7.010	2.000	2.000		
A-14	✓	5451120	7.210	2.200	2.200		
验货结论/结论 Conclusion							
综合评价/ Evaluation Level							
非常满意 Very satisfied	✓	满意 Satisfy	一般 Normal with defects	不满意 not satisfied	非常不满意 bad		
备注/Remarks							
发货通过, 可以发出 Pass, shipping proceed	发现问题, 改正原出货, 如因此影响交期而造成的一切后果由工厂负责 Defects need to be fixed before shipment, all the costs that resulted on delivery time should be burdened by warehouse.						
问题严重, 不得发出 Fail, no shipment	因起缺陷等问题造成, 风险由工厂负责 If shipment without fix the defects, the risks and costs shall be burdened by factory.						
注: 此验货报告不作为产品合格的质量依据。 PS: This inspection report shall only be the reference for products inspect.							
检验员 Signature of inspector		生产负责人签字 Signature of manager					

Part.2 Inspection Report

Every inspection and production will be recorded for later reference. The acceptance audit shall be conducted regarding relatively defined check items.

All inspection procedures must be performed in accordance with the inspection standard.

Products need to be improved or remade if any defect appears. The inspection records (for example, shipment samples, inspection report files, photos, ...etc.) will be kept in case any tracing is needed.

Part.2 Inspection Team

Sunwing has a professional inspection team responsible for the four quality control processes.



IQC: inspect raw material and preproduction



IPQC: inspect product's production process



FQC: finished products are qualified



OQC: check if package meet shipping requirements

Part.3 Inspection Equipment

To help the inspectors improve their work efficiency, we have different inspection instruments such as to check color, weight, and performance, etc.



If you have any questions regarding the quality control system, welcome to discuss with us through sales@plantsartificial.com.